CONSULTANTS SPECIALIZING IN

Civil and Sanitary Engineering, Ground Water Geology and Irrigated Agriculture

Norman, Oklahoma: Elburn, Illinois

P. O. Box EE

Elburn, Illinois 60119

Phone (312) 557-2550

EPA Region 5 Records Ctr.

February 17, 1977

FEB 92 1977

El morassico Palestica (1998)

D & N Trucking Company Rt 3 Box 186 Oswego, Illinois 60543

Gentlemen:

This letter is to report the well elevations and water level elevations for the monitoring wells constructed at the By-Pass 30 - Albright Road property as follows:

Well No.	Top of Well Elevation	Depth to <u>Water</u>	Water Elevation
1	102.38	25.31	77.07
4 -	100.44	14.29*	NA
5	108.67	24.45	84.22
6	112.72	29.83	82.89
7	105.56	19.23	86.33

Water Not Encountered at Total Depth

3M=Spot Painted on Concrete at West Corner of (East) Overhead Door Nearest Office

REGISTERED

Respectfully submitted,

ENGINEERING ENTERPRISES, INC.

James K. Michels, P.E.

Vice President

JKM/cab

Enclosure